



Machine redesign before season 2015


In recent months, we've made a number of corrections, changes and improvements of our machines, mainly:

- avoiding closed steel sections in the supporting structures for open structures, channel sections or bent structures which eliminates gaps, hard-to-reach dead ends, sharp corners and protruding parts, and thus increasing the hygiene standard and facilitating cleaning.
- all the flat upper surfaces are currently slant, which facilitates cleaning and prevents from collecting water, dust and dirt, as it was on flat surfaces.
- new type and construction of safety housings they are more hygienic, easier to clean and use.
- increased electrical standard means safer and easier handling and more efficient diagnosing possible future failures















MASTER FF 3000






MASTER FF 3000

www.icegroup_•pl










RIPPLE PUMP **WITH HOPER**







COMMERCIAL DIVISION

L. Arkadiusz Geratowski

President and Commercial Director



Mariusz Goik General Manager and Vice President





Reema Tomaszewska-Handall

Commercial Division Coordinator



Ewa Bernacka

Commercial Division Administrator



Agnieszka Ganczorz

Export specialist



Aleksander Zinkowski

AFTER-SALES AND CHNICAL SUPPORT DIVISION



Wojciech Kowalski

Technical Director



Paulina Szyszka



Piotr Marcol



Sonia Pawka





Dilara Hajruddinowa